


Charter Township of Texas Flood Study

Figure


Eagle Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


Crooked Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


Bass Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


Pine Island Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


Duck Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


Pretty Lake Monitoring Results



Charter Township of Texas Flood Study

Figure


8th Street Monitoring Results



Charter Township of Texas Flood Study

Figure


12th Street Monitoring Results



Charter Township of Texas Flood Study

Figure


Al Sabo Monitoring Results



Charter Township of Texas Flood Study


Figure

Sun Valley Monitoring Results



Charter Township of Texas Flood Study

Figure
USGS Monitoring Results



Charter Township of Texas Flood Study

Figure

USGS Kalamzoo River at Comstock Park Monitoring Results

